

ECS operational staff meeting household appliances decision sheet			OSM HA N°455
Sub cl.	Meeting	Agenda item	Document
19.101+24.1.4	24	6.3.2	CLCTC61SEC1769
Standard	EN 60335-2-34:2002	Date	2017-02-08
Question	<p>In the recent meeting CLC/TC72 in Zurich discussed an issue originating from an incorrect interpretation by a testlab of the data on certificates of thermal motorprotectors to EN 60730-2-4 having to do with the testing of motorcompressors. The endurance tests of the motorprotector are performed together with the motorcompressor and the protector certificate does not include endurance data. However sometimes protector manufacturers add endurance data to the certificate which in effect has no value. The incorrect interpretation resulted in requesting additional motorcompressor samples using a protector having a certificate according to the standard versus one with additional data. CLC/TC72 decided the interpretation was incorrect and through BT asked CLC/TC61 to consider the matter.</p>		
Decision	OSM/HA agrees with the CLC/TC72 interpretation and the endurance test of motor protectors in motor compressor can only be done mounted together according clause 19.101of EN 60335-2-34		
Explanatory notes			